Approved For Release 2002/08/21 ARDP89B00569R000400080067-0

OPERATION

25X1A

2-8 OCTOBER 1959

Cy #2 Destroyed
by 12 July 82

25X1A

TS # 160486 Copy 2 of 5 Page 1 of 29

OPERATION

25X1A

2-8 OCTOBER 1959

BRISHMENT NO.

AND EMPERE OF SLASS. []

AND EMPERED TO TS (\$) 8 2006

PARTS 10/6/86 REVISIONERS (\$) 0/94258

TS #160486

Copy / of <u>5</u> Page / of <u>29</u>

Approved For Release 2002/08/21 CIA-RDP89B00569R000400080067-0

INDEX

OPERATION	

25X1A

I - GENERAL SUMMARY

II - TIMETABLE

III - PICTORIAL ILLUSTRATIONS

IV - INDIVIDUAL SECTION COMMENTS

A - PERSONNEL

B - 1 - OPERATIONS

25X1C

2 - DETACHMENT REPORT

3 - WEATHER

4 - PERSONAL EQUIPMENT

C - MAINTENANCE

D - SPECIAL EQUIPMENT


E - COMMUNICATIONS

F - SECURITY

G - MEDICAL

TS #160486

Copy \angle of $\frac{5}{29}$ Page 2 of 29



I - GENERAL SUMMARY

TS #160486

Copy / of 5 Page 3 of 29

AP STORT

2	_	V	4	Λ
_	ວ	Λ	-1	А

	ı			
OPERATION	2 -	8	OCTOBER	<u> 1959</u>

,	
25X1A	1. MISSION OBJECTIVES: The requirements for were outlined in Headquarters Operations Order 11-59 and encompassed two
25X1A	objectives:
	a. Exercise the "fast move" concept (See Detachment 10-10 Operations Plan 42-59, 1 April 1959)
	b. Obtain weather data to further substantiate MEU weather story.
	2. STAGING:
	a. <u>Preparation</u> : The mobility gear as outlined in Operations Plan 42-59 was used on this operation.
25X1A	b. <u>Pre-deployment</u> : The support aircraft, a C-130, arrived 4 October 1959. The C-130 landed, was loaded, refueled, cleared and airborne in two hours.
	c. Movement: A total flying time of 10 hours and 45 minutes was required to place the unit at
25X1A 25X1A	d. Staging Area: Construction at prevented the use of our original hardstand, but personnel, with their usual eagerness to help, cleared an area about 300 yards from the control tower and we had most of the infield of the airdrome to ourselves. Setting up for the first mission has become strictly routine. Things went into place without snags within 2 hours and 30 minutes.
	e. Post-deployment: The C-130 was loaded and ready for departure within two hours after the U-2 was launched for return for home base.
	3. CONCLUSIONS: The "fast move" concept is very workable. The timing factors are valid. Reliability and security are maintained.
25X1A	4. RECOMMENDATIONS: Recommend that base facilities set aside at be utilized for all missions flown from there.

TS #160486

Copy / of 5 Page 4 of 29
Approved For Release 2002/08/21 : AREP89800569R000400080067-0

II - TIMETABLE

AT STORET

TS #160486

Copy \angle of $\frac{5}{29}$ Page $\frac{5}{5}$ of $\frac{29}{29}$

Approved For Release 2002/08/21	RDP89B00569R000400080067-0
Approved for Release 2002/00/2 is	

Approved For Release 2002/00/21							
	TIMING ((ALL TIMES GMT)	25X1A				
SCHEDULED	ACTUAL	ACTION	25X IA				
02/0600	02/0600	C-54 departed					
02/0700	02/0700	C-54 arrived	25X1A				
03/0900	03/0900	C-54 departed]				
03/1135	03/1135	C-54 arrived	25X1A				
04/0900	04/1000	C-130 departed	25X1A				
04/1900	04/2045 *	C-130 arrived	25X1A				
05/0100	05/0100	U-2 349 departed	25X1A				
05/0600	05/0630	U-2 349 arrived	25X1A				
05/1000	05/1015 **	U-2 349 departed	(mission)				
05/1600	05/1625	U-2 349 arrived					
06/1000	06/0900 +	U-2 349 departed	(mission)				
06/1600	06/1535	U-2 349 arrived					
06/2000	06/1740	U-2 349 departed	25X1A				
07/0100	06/2245	U-2 349 arrived					
07/0300	08/0950 ++	C-130 departed	25X1A				
07/1300	08/1945	C-130 arrived	25X1A				
* C-130 landed a	at to change	e crew	25X1A				
** U-2 takeoff de	played 15 minutes of	due to Personal Equipment					
		or 24 hours 25X	+ U-2 took of one hour early 25X1C ++ C-130 departure delayed, AOCP for 24 hours				

TS #160486


Approved For Release 2002/08 CIA-RDP89B00569R000400080067-0


III - PICTORIAL ILLUSTRATIONS

TS #160486

Copy \angle of \leq Page \neq of \leq 29

THE SECRET







INSIDE PORTABLE HANGAR
PREFLIGHT INSPECTION ON U-2

TS #160486

Copy \angle of $\underline{\mathcal{S}}$ Page $\underline{\mathbb{Z}}$ of $\underline{\mathcal{Z}}$

Approved For Release 2002/08/21 : CIA-RDP89B00569R000400080067-0






U-2 IN POSITION BEHIND C-130 PRIOR TO REFUELING

TS #160486

Copy \angle of \leq Page \neq of \neq






PILOT LOADING FOLLOWING NORMAL PROCEDURE
THE START-UP POINT, 300 YARDS FROM THE ACTIVE RUNWAY

TS #160486

Copy / of 5 Page / of 27 Approved For Release 2002/08/21: CIA-RDP89B00569R000400080067-0





X1

25X1

ILLEGIB

UNIT AND TOOL HACKS UNDER G-130 WING TOWING U-2 TO START-UP POINT 45 MINUTES PRIOR TO TAKEOFF 75 /74604**36**

Copy \angle of 5Page 2 of 2 Approved For Release 2002/2011 CIA-RDP89B00569R000400080067-0

IV - INDIVIDUAL SECTION COMMENTS

JA SECRET

TS #160486

Copy $\frac{1}{12}$ of $\frac{5}{29}$ Page $\frac{1}{12}$ of $\frac{5}{29}$

25X1A

Next 1 Page(s) In Document Exempt

Approved For Release 2002/08/21 : CIA-RDP89B00569R000400080067-0

25X1A

	B-1	-	0	P	ΣR	A'	ΓI	0	NS	:
--	-----	---	---	---	----	----	----	---	----	---

	1. COMMENTS:	ļ	
25X1A 25X1A	a. 4 October 1959: At 0740Z the C-130 support aircraft landed at The C-130 was refueled and the staging gear loaded by 0845Z. A refueling stop was made at	25)	< 1A
25X1A	to pick up crew augmentation for the C-130. Arrival at was finally made at 2045Z. Upon landing, personnel cleared customs and then assisted in unloading and assembling the staging gear at the	25)	< 1A
	support aircraft. Following the unloading operations personnel established liaison with air traffic control. was very cooperative, as they always have been. Due to transmission difficulties	25)	< 1A
	the came in garbled at Weather was looming as a problem to mission BF 59-11 and with the concurrence of headquarters	25	< 1A
	operations dispatched a message to the communications center at 2310Z to delay the departure of BF 59-11. Equipment malfunctions in the	- 1	<1A
	communications center delayed the message until BF 59-11 had already departed. At this time prepared for a possible diversion. We	ļ	<1A <1A
	got a break from the weather and mission BF 59-11 was successfully con- cluded at 05/0630Z.	23)	ΧIA
	b. 5 October 1959: Mission 314 proceeded on schedule up until the last pressure test made by Personnel Equipment. At that time a face-		
)EV1	plate seal ruptured. Personal Equipment made an excellent recovery through the use of an A-13 oxygen mask. was equipped with		P.
25X1A	a replacement helmet and mission 314 was launched at 1015Z. The mission was successfully concluded at 1625Z.		
	c. 6 October 1959: Due to conflicting with that of mission 315 we launched 315 at 0900Z. Mission	(10	
·	315 landed at 1535Z. We were shooting for a 1730Z launch for mission BF 59-12, but this takeoff was delayed for ten minutes due to non-receipt of weather information that had been requested. Mission BF 59-12 landed at 2245Z.		
25X1A	d. 7 October 1959: The staging party had intended to depart	25	〈1A
	at 0900Z but was delayed 24 hours as a result of a fire warning system malfunction in the C-130.	23	VIΛ
	e. <u>8 October 1959</u> : The staging party departed at 0950Z after a one hour and fifty minute delay due to local weather phenomenon	25	< 1A
25X1A	(fog). A refueling stop was made and the final leg of Operation was completed at 1950Z.	25	(1C
	2. <u>CONCLUSIONS</u> : Operation confirms that the "fast move" 25 concept is both a workable and flexible method of operation.	5X1	4
	3. RECOMMENDATIONS:		
	TS #160486		
	Copy / of 5 Page /5 of 29		,
	THE SECRET		

Approved For Release 2002/08/21 : DP89B00569R000400080067-0

OPERATIONS (Continued)

	a. To prevent snags caused by communications difficulties the staging should have canned routes when they depart 25X1/
25X1A	b. The
25X1A	c. The support C-130 should be under operational control of commander while at and the staging commander while
25X1A	throughout the operation at and the staging commander while enroute and
25X1A	d. be given a conv. of the Committee of
25X1A	flaps caused by misunderstanding the goal of the exercise. For Example; message 2421 (IN 12291).
25X1A	

TS #160486

Approved For Release 2002/08/21 : CIA-RDP89B00569R000400080067-0

	• • • • • • • • • • • • • • • • • • • •
25X1C	DETACHMENT REPORT
25X1A	1. MOVEMENT: The people concerned traveled to with the
25X1A	advance commo party in the C-54 leaving on the 2nd of October. After a night stop at the C-54 arrived at at 1235
25X1A	local on the 3rd of October having landed at the clear metans
25X1A	Customs clearance took nearly an hour. The customs officer concerned ha no prior warning of our arrival and the make-up of the party. This
25X1A	caused delays in obtaining customs clearances.
25X1A	2. ARRIVAL:
25X1A	a. On arrival at the commo equipment was installed in the assigned room in the hangar. The arrangements in the hangar were vastly improved since the last detachment, all rooms had additional electric heating installed and the commo room was now secure.
	b. The main party arrived on the evening of Sunday the 4th of October by C-130. Local customs arrangements had been made and these were quickly completed.
25X1A	c. Due to construction work in progress on the perimeter track, the aircraft dispersal used on was not available. The C-130 was positioned to receive the U-2 on a hardstanding approximately 100 yards from ATC and about 300 yards from number two hangar. While the position was sufficiently isolated to deter visitors, the proximity to ATC and the hangar was found useful for communications purposes.
	3. ACCOMODATION AND MESSING: All detachment personnel were housed in either officers or sergeants mess. Most of the detachment using the officers mess were housed in the prefabricated annexes, the main building was full with other visitors. The accomodation was good, but no

4. OPERATIONS:

- a. The operation went as planned with only slight variations from the timing in the Operations Order. The arrival of the U-2 on the 5th at 0630 hours (after the attempt to delay its departure) was without incident due to a fortuitous improvement in the local weather.
- b. The first weather mission 314 was delayed 15 minutes due to a leak in the helmet bladder which necessitated a change in helmets.

central heating was available due to work in progress on the boiler system. The hot water supply for washing was also easily exhausted. The mess staff were again most helpful in catering to our needs.

c. The second weather mission 315 was brought forward one hour to avoid interference with a local air exercise. Both missions were without incident and the equipment worked well, particularly the RADAN, which apparently will work over various sea states.

H SIGHT

TS #160486 Copy / of 5 Page /7 of 29 B-2

Approved For Release 2002/08/24 ARDP89 00569R000400080067-0

25X1C	DETACHMENT REPORT (Continued)
25X1A 25X1C	d. On both flights, a certain amount of explanation was needed over the R/T toControl to get a descent into Apparently a word preface to our number call sign would help in identifying us with and
25X1A 25X1A	e. The ATC staff at were again most helpful and cooperative. It must be appreciated, however, that they are not staffed for 24-hour operations and once they have been stood down, it is difficult to assemble all of their crews at short notice in the early hours of the
25X1A	morning. 5. RECOMMENDATIONS: a. The customs at be given notice of the arrival of the advance party, with some explanation of what to expect.
25X1A	b. On all weather missions out of a word prefixed call sign be used.

TS #160486 Copy __ of <u>5</u> Page <u>/8</u> of <u>29</u>

B-3 - WEATHER

1. <u>COMMENTS</u>: Weather package number two performed the best of all previous operation. RADAN especially functioned above expectation. Malfunction of data reference and time channel occurred during BF 59-11. Problem was isolated and corrected as soon as possible after mission 314. No further difficulties encountered.

2. RECOMMENDATIONS: In future weather staging recommend ground battery cart (rectifier type) be used for ground power. The MA-l impedes proper calibration of humidity and temperature elements of weather package.

TS #160486

Copy / of 5 Page /9 of 29

THP SEGNET

47 00011

Approved For Release 2002/08/21: CIA-RDP89B00569R000400080067-0

B-4 - PERSONAL EQUIPMENT

1. COMMENTS:

25X1A

- a. Arrived at _______4 October aboard C-130 aircraft. Unloading of aircraft was accomplished very quickly and preparations made to accomplish first launch from the C-130. The Personal Equipment section was set up in the forward hold. This was done with a minimum of time and effort, however, some difficulty was encountered from lack of proper lighting.
- b. Pre-breathing for the first mission was accomplished without indication of equipment malfunction. After suiting up pilot he was placed on test stand for final check. With mission faceplate in place and pressure "on" a leak was indicated. Upon inspection the leak was found to be a very small hairline perforation in the faceplate seal along the chin line. (Believed to have been caused by faceplate pinch.) A rapid change to a substitute helmet was affected by using an A-13 type oxygen mask. The procedure used to do this was as follows: With regular faceplate still in place, have pilot hold his breath, remove faceplate and he will remove the helmet from his head. Have the oxygen mask ready and when helmet is clear place mask, which is set at a 30M pressure firmly against his face. When he has breathed for several seconds have him again hold his breath and the substitute helmet is quickly donned. Snap regular faceplate in position as soon as helmet is completely on. Neck seal adjustment can then be made. The checkout was completed without further incident. This procedure worked very well and posed no extreme problem for anyone concerned.
- c. The gauge on one walk-around bottle malfunctioned causing the bottle to run out with an indication of 300 pounds on the gauge.
- d. The launch was accomplished without further difficulty fifteen minutes after scheduled takeoff time.
- e. For the second mission personal equipment was moved into a permanent type building. The accommodations here were good with adequate room and lighting.
- f. The second launch was accomplished without incident and on schedule.
- g. The compartmented Personal Equipment box on casters works extremely well. Being so designed that all equipment has a place and when opened and in proper position everything is readily accessible.

2. RECOMMENDATIONS:

a. That an A-13 type oxygen mask be included in Personal Equipment staging box.

TS #160486

Copy / of 3 Page 20 of 29 A SECRET

Approved For Release 2002/08/21 : CPR DP89B00569R000400080067-0

PERSONAL EQUIPMENT (Continued)

- b. That two portable spotlights be carried by Personal Equipment on all stagings.
- c. That a 28-volt aircraft battery be carried for use with test stand.
- d. Walk-around bottles will be changed each fifteen minutes regardless of gauge reading.

TS #1604**86**Copy / of 5
Page 2/ of 29

er deliej

Approved For Release 2002/08/21: CIA-RDP89B00569R000400080067-0

C - MAINTENANCE

25X1A

COMMENTS: The operation was considered a success by the maintenance section. The amount of personnel utilized for the operation was sufficient. The spare parts brought along were adequate. The times used for between flight maintenance were realistic. The cooperation between sections was excellent.

TS #160486

Copy / of 5 Page 22 of 29

AF SECRET



Approved For Release 2002/08/21: CIA-RDP89B00569R000400080067-0

D - SPECIAL EQUIPMENT

1. GENERAL: Special Equipment was alerted for two tracker missions. Equipment loaded aboard C-130 per Operations Order 42-59, modified to eliminate "B" equipment and supplies. No problems encountered.

2. EQUIPMENT:

a.	Power cart with 28 VDC and 15 VAC	290 lbs	18 cube
b.	Spare tracker in shipping case	100 lbs	8 cube
c.	Supply cart with support equipment	115 lbs	4 cube
d.	Hatch dolly	140 lbs	44 cube

25X1A

3. UNLOADING The C-130 was unloaded with no problems. The Special Equipment section assisted in erection of tent and placement of material.

4. OPERATIONS:

- a. Tracker loading was accomplished in the C-130 for the first mission and in the hangar for the second mission. Power to operate the power cart was obtained from the 115 VAC ONAN generator. No problems encountered.
- b. Mission 314. Tracker SN 12 in operation and loaded in article 349 on schedule. 100% operation for 650 feet.
- c. Mission 315. Tracker SN 7 in operation and loaded in article 349 on schedule. 100% operation for 635 feet.

25X1A

5. CONCLUSION AND RECOMMENDATIONS: Recommendations from Operation were utilized on this mission. No problems were encountered. No further comments or recommendations.

TS #160486

Copy $\sqrt{}$ of $\sqrt{}$ Page $\sqrt{}$ of $\sqrt{}$ $\sqrt{}$

JAP SECRET

Approved For Release 2002/08/21: CIA-RDP89B00569R000400080067-0

	<u>E</u> -	COMMUNICATIONS
	1.	PERSONNEL:
	(CT	a. The Communications Team consisted of cryptographers '/C's) and wire equipment technician (WE/T).
b. The senior CT/C was designated as the Communications Leader for this operation. The WE/T, in addition to install Signal Center equipment, was responsible for checking out the ground communications equipment and such assistance as possible equipment installed in aircraft 349.		
	2.	SIGNAL CENTER INSTALLATION:
		a. A permanent signal center installation was made.

- b. The equipment installed includes the following:
- (1) Two TG-26A field teletypewriter sets used as terminal equipment.
- (2) Two M-19 teletypewriter sets and associated cryptographic equipment.
 - (3) Ancillary equipment.

25X1A

3. STAFF COMMUNICATIONS:

- a. Communications between and the relay station were established via landlines provided by the GPO.
- b. Traffic to headquarters was transmitted via direct patch circuits. Traffic to lateral stations were transmitted by the tape relay method.

25X1A 4.

25X1A

25X1A

25X1A

25X1A

25X1A

- a. System III-A was installed in article 349 at and flown to with its main power switch turned off.
- b. A spare recorder was installed in the cockpit of 349. This was done in case headquarters requested a system III capability on mission 315 as well as on mission 314.
- 25X1A c. The systems main power switch was turned on by the WE/T at prior to launching of mission 314.
 - d. Upon completion of mission 314, the system III recorder was removed and the spare recorder installed for mission 315.

TS #160486

Copy $\sqrt{}$ of $\sqrt{}$ Page $\sqrt{24}$ of $\sqrt{29}$

W Secret

Approved For Release 2002/08/21 : CIA-RDP89B00569R000400080067-0

	COMMUNICATIONS (Continued)
>	e. With the completion of mission 315, the systems main power switch was turned off and the system deadheaded back to
25X1A	5. AIR/GROUND COMMUNICATIONS:
	a. Spare equipment consisted of two ARC-34 sets and one ARN-6 set with spare control head.
	b. The ARC-34 and ARN-6 equipment was checked out prior to each flight by the WE/T.
	6. <u>RECOMMENDATIONS</u> :
IA	a. The Communications Team, on this type of staging, should consist of one additional team member. This will permit the team leader to effect closer coordination of communications activities and maintain closer liaison with the operations section.
	b. The flying of more than one mission during a forward staging is a move away from the fast move concept. Under the fast move concept, the maintenance of systems at the forward staging

are has never been considered.

25X1A

25X1A

TS #160486

Copy $\frac{1}{25}$ of $\frac{1}{29}$

11 0. Juli

Approved For Release 2002/08/21: CIA-RDP89B00569R000400080067-0

	F - SECURITY
25X1A	1. GENERAL COMMENTS:
25X1A	a. Security personnel participated in the staging.
25X1A	b. On 3 October at 0955 hours, departed via C-54 number 72627 as courier with the advance party arriving at at 1330 hours on the same date.
25X1A	
25X1A	c. Upon arrival of the advance party the hangar was inspected and necessary arrangements made for the arrival of the main party.
25X1A	d. On 4 October the main party departed Security personnel
25X1A	included were
25X1A	e. Upon arrival the support aircraft was unloaded and the portable hangar was erected.
	f. On 5 October the primary vehicle arrived. It was preflighted and launched on the first mission, using the C-130 and portable hangar. Retrieve was made without incident. The portable hangar was dismantled and the entire operation moved into the permanent hangar.
25X1A	g. On 6 October the second mission was launched and retrieved without incident. On this same date the primary vehicle was launched for return to
25X1A	h. On 7 October the support aircraft was AOCP and departure of the staging party was not until 8 October. Arrival was made at on the same date.
	2. CONCLUSIONS:
25X1A	a. Security was adequate in all respects. Both advance and main parties were given a security briefing prior to departure from One or more security personnel accompanied each support aircraft and acted as official courier.
05)/44	b. One or more security personnel accompanied the primary vehicle while being launched or retrieved. While the vehicle was on the ground it was under constant observation by security personnel.
25X1A	c. The exterior of the permanent hangar was patrolled by
25X1A	(with sentry dog at night) and interior guard was by detachment

TS #160486

Copy $\frac{1}{26}$ of $\frac{1}{29}$ Page $\frac{1}{26}$ of $\frac{1}{29}$

H SINI

security personnel.

Approved For Release 2002/08/21 C/A RDP89B00569R000400080067-0

SECURITY (Continued)

- d. There were no security or personnel incidents.
- 3. RECOMMENDATIONS: It is recommended that the Senior Security Agent on stagings maintain control of the cargo and passenger manifests. Also, that not less than six copies of each manifest be made. That a portable typewriter and blank manifest forms be carried on future stagings.

TS #160486

Copy $\frac{1}{27}$ of $\frac{5}{29}$

Approved For Release 2002/08/21 ARDP89B00569R000400080067-0

G - MEDICAL

1. GENERAL:

- a. MEDICAL FACILITIES: At this staging base these are adequate to meet any medical emergency. They are backed by two hospitals within thirty miles. No health problems were encountered during this short stay. Number of persons receiving medical care: four.
- b. <u>HYGIENE AND SANITATION</u>: Good. The newly decorated rooms adjacent to our hangar are excellent. Unfortunately the heating in the middle room was inoperative.
- c. MESSING: Again the staff of the Officers Mess were very cooperative in providing our meals at unusual hours. Food and beverages brought to the C-130 prior to the launching of 5 October was appreciated by the ground crew who had had no time for breakfast.
- d. <u>SLEEPING ACCOMODATION</u>: Nearly all the staging party were installed in the "Seco" type hut accomodation. This accomodation was satisfactory as the weather remained clement. The hot water system in the smaller of the annexes was inadequate to provide either pilot with enough hot water for his post-flight bath or shower, which are taken in the late afternoon.
- e. <u>PREBREATHING</u>: Prior to the launching of the first mission on 5 October the pilot prebreathed in the forward part of the C-130 cargo hold, lying on a cot between sheets and blankets. This arrangement is satisfactory in a temperate climate from April through October. When the suit and helmet were inflated by press-to-test a leak was found in the faceplate seal of the helmet bladder. It was found to be a hairline nick in the bladder. A change of helmet bladder could be affected as there was available on the C-130 some A-13 oxygen masks. One of these masks was used so that the level of denitrogenation was not lost. The presence of the oxygen mask coupled with the recent information received from Headquarters on denitrogenation rates gives assurance that helmet changes can be readily accomplished without hazard to the mission.
- f. ATTENDANCE OF MEDICAL OFFICERS AT LANDINGS AND LAUNCHINGS: The Senior Medical Officer at the staging base was in attendance for the landing of the first ferry flight, not having been briefed that the staging party included a doctor.
- 2. <u>CONCLUSIONS</u>: A few further improvements would iron out these minor snags.

3. RECOMMENDATIONS:

a. That the present setting of the thermostats for heat controllin the rooms adjacent to the hangar be raised during cold weather to give

TS #160486

THE SECURI

Copy / of S Page Z8 of Z9

Approved For Release 2002/08/21 - A-RDP89B00569R000400080067-0

MEDICAL (Continued)

a room temperature of 70 degrees (Fahrenheit). We are dealing with a near naked man, before dawn on a winter's day prior to a long flight. I consider it essential that he gets into the cockpit warm.

- b. That food and beverage warmers be supplied for conveyance of meals and snacks to the ground crew when quick turn-arounds prevent them attending mess meals. (Changing from working clothes to suits consumes time)
- c. That improvement in the heating of the large mess annex be considered. A cold air bath at 0400 hours is not conducive to efficiency or manual dexterity.
- d. That provision is made to ensure enough hot water for the pilots after these long flights.
- e. That in cold conditions the cargo hold of the C-130 is closed, and the hold is heated before the pilot prebreathes and prior to and during suiting up. In hot climates, that the hold be cooled.
 - f. That two A-13 oxygen masks be carried in the personal equipment.
- g. That the Senior Medical Officer at the staging base be briefed that the staging party carries a doctor.

TS #160486

Copy / of <u>S</u>
Page <u>Z9</u> of <u>Z9</u>

Approved For Release 2002/08/21 : CIA-RDP89B00569R000400080067-0

HA SECTION